

DET NORSKE VERITAS  
TELEFAX/FACSIMILE



DATE: 1997-07-03	OUR REF.: SEA-6001-97
TO: Belzona Washington Inc.	
ATTN: Mr. Clyde A. Laughlin	
FAX NO: 206-340-0715	
FROM: Drummond Brigham	
NO. OF PAGES (incl. this): 2	
COPY TO: C. King	

If not received properly, please call +1 425 861 7977

DET NORSKE VERITAS

*DNV Seattle*  
14450 N.E. 29th Place, Suite 217  
Bellevue, Washington 98007-3697  
USA

Telephone:  
+1 425 861-7977  
Telefax/Facsimile:  
+1 425 861 0423  
Org. No. VAT

**F/V PACIFIC GLACIER**

Dear Mr. Laughlin:

Thank you for your quick response to inspect both Port and Starboard tailshafts of the fishing Vessel PACIFIC GLACIER at Todd Pacific Shipyards on Wednesday, 25 June, 1997.

Enclosed with this fax is a copy of DNV correspondence regarding Belzona's working procedures for "TSW 100" and "SOS-6". Please be advised the criterion for acceptance of Belzona corrosion protection on tailshafts or any other shipboard machinery is on a case by case scenario at this time.

If you have any questions or comments, please do not hesitate to contact me.

Yours faithfully  
for Det Norske Veritas

Drummond Brigham  
Surveyor



DATE: 1997-04-21	OUR REF.: DTP244-15651-J-85
TO: DNV Seattle	
ATTN: Ches King	
FAX NO: +1 206 861 0423	
FROM: DTP244 / Machinery and Pollution Prevention	
NO. OF PAGES: 1	
COPY TO:	

If not received properly, please call: +47 67 57 90 22

DET NORSKE VERITAS AS  
DIVISION TRAINING AND  
PRODUCTS

Veritasveien 1  
N-1322 Høvik, Norway  
Telephone:  
+47 67 57 99 00  
Telefax/Facsimile:  
+47 67 57 99 11  
Reg.No. NO 945 748 933 MVA

**PACIFIC GLACIER, Id.no. 15651  
COATING WITH BELZONA OF NEW PROPELLER SHAFT**

We refer to earlier correspondence and telephone conversations with Mr Lasse Norhamo regarding above mentioned subject.

As shown in approval letter of Friday 18. of April 1997 with copy to you, the shaft is now approved and details of the coating will be clarified directly to you in this letter.

We accept that Belzona Ceramic S-metal is used as corrosion protection if the following conditions are fulfilled:

- The procedure is to be Belzona Working recommendation TSW 100 to be in accordance with ABS and Lloyds approvals. Please observe that TSW 100 is NOT the same as Belzona know-how SOS-6.
- The surveyor should be present to verify the application procedure of the Belzona coating according to TSW 100.

We have little experience with Belzona coatings, but accept it on a case by case basis according to the ABS and Lloyds approvals. Please note that the inspection intervals on the Belzona coating on the shaft will be 2.5 years.

If you have any questions or comments, please do not hesitate to contact us

Yours faithfully  
for DET NORSKE VERITAS AS

  
Tor Erik Andersen  
Head of Section

  
Arne Torstensen

Reference is made to Section 13 of the Statutes of Det Norske Veritas relating to limitations of liability which will apply for this document